Asbestos Survey for

Hall & Woodhouse Ltd

at

True Lovers Knot
Tarrant Keyneston
Blandford
Dorset
DT11 9JG



Project Number: AS04121 - True Lovers Knot

Printed: 01/11/2008 By: JTEC Environmental Ltd.. Using Multibase software.



Names and Addresses

Fax:

Fax:

Client Name:

Hall & Woodhouse Ltd

The Brewery

Blandford St Mary

Dorset

DT11 9LS

Contact:

Phone: 01258 452141

Instructing Party:

Hall & Woodhouse Ltd

The Brewery

Blandford St Mary

Dorset

DT11 9LS

Contact: James Overy

Phone: 01258 452141 Fax:

Site Full Name:

True Lovers Knot

Tarrant Keyneston

Blandford

Dorset

DT11 9JG

Contact:

Phone:

Report Author:

JTEC Environmental Ltd.

Tansley Cottage, Shave Lane,

Todber,

Sturminster Newton,

Dorset.

DT10 1JA

Contact: John Chilvers

Surveyor

Phone: 01258 821398 Fax: 01258 821398

JTEC Environmental Ltd.

Project Number:	S04121 - True Lovers Kn
Survey Date:	09 August 2004
Printed On:	01 November 2008
Page:	Page 1 of 1



TABLE OF CONTENTS

SECTION 1	Site Description
SECTION 2	Survey Drawings
SECTION 3	Survey Objectives
SECTION 4	Survey Techniques
SECTION 5	Survey Caveat
SECTION 6	Survey Notes
SECTION 7	Survey Summary
SECTION 8	Survey Recommendations
SECTION 9	Material Assessment: Summary by Area
SECTION 10	Material Assessment (Photo)
SECTION 11	Bulk Identification Report
SECTION 12	Priority Assessment: Summary by Area
SECTION 13	Priority Assessment (Photo)
SECTION 14	Excluded Areas



SECTION ONE

SITE DESCRIPTION

Site Description

General Information:

This building is well in excess of 100 years old and is of brick construction. Several improvements have been made over time with the main one being the addition of a storeroom. Few ACM's (asbestos containing materials) have been found.

Area	Comments	Acc	essed
•	Samples taken & presumed asbestos materials present, asbestos materials present in samples.		Yes

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kno
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot. Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Site Description:	Page 1 of 1



SECTION TWO


SURVEY DRAWINGS



Survey Drawings and Documentation

Project Number:

AS04121 - True Lovers



Description of Drawing:


Ground floor layout



Survey Drawings and Documentation

Project Number:

AS04121 - True Lovers



Description of Drawing:

First and second floor layout.

SECTION THREE

SURVEY OBJECTIVES

Survey Objectives

- Produce a report, in a database format, indicating areas containing identified and suspected asbestos based materials, including photographic records of asbestos occurences where possible.
- 2 To carry out a survey to ascertain the presence of asbestos based materials.
- 3 To include a risk assessment for each individual Sample.

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Survey Objectives:	Page 1 of 1



SECTION FOUR

SURVEY TECHNIQUE

Survey Technique

- 1 Materials of a similar type were only occasionally sampled and it was assumed that other surfaces identical to where the sample was taken, was of a similar composition.
- 2 Photographs were taken at all of the sample locations (unless otherwise stated).
- 3 Samples were returned to the Main Laboratory for analysis.
- Asbestos Bulk Sample Analysis is conducted by using Polarised Light and Dispersion Staining Techniques. Dispersion Staining is used to describe the colour effects produced when a transparent colourless particle or fibre is immersed in a liquid having a refractive index near to that of the particle or fibre, and is viewed under a microscope using transmitted white light (based on HSE Publication MDHS 77).

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Survey Technique:	Page 1 of 1



SECTION FIVE

SURVEY CAVEAT

Survey Caveat

- This report is based upon a non-destructive inspection of an unfamiliar site. During the course of the survey all reasonable efforts were made to identify the physical presence of materials containing asbestos within the areas of the building which are subject to future refurbishment works. It is known that asbestos materials are frequently concealed within the fabric of buildings or within sealed building voids so that it is not possible to regard the findings of any survey as being definitive. It must always remain a possibility that further asbestos containing materials may be found during refurbishment or demolition activities. For reasons set out in this report, the results cannot give an assurance that all asbestos materials have been found and must not be thought to do so. The nature of the survey was a non-destructive inspection at key locations of accessible voids and areas. From the evidence of the inspections and of the sampling and analysis undertaken, it is clear that asbestos containing materials are either present or within or associated with various areas as detailed in the report. We recommend that samples be taken of suspect materials which may be uncovered within the listed areas or within the areas of the site which were not included in this survey.
- From mid 2005, sample analysing laboratories do not provide information on the amounts of asbestos fibre present within materials as their UKAS or equivalent accreditation does not permit this. Therefore any reference to the concentrations of fibres that appear in any survey report are only approximations and are intended for guidance only.

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Survey Caveat:	Page 1 of 1





SECTION SIX

SURVEY NOTES

Survey Notes

- Whilst every effort was made to locate the ceiling panels, wall partitions and other panels, which may have been constructed from asbestos boarding, none other than those detailed were found. Some may have been missed due to repairs, alterations etc, where false and other finishes have been applied or where different specifications (including a possible mixture of asbestos and non-asbestos) panels have been used in the same area. Only by sampling each panel would the composition of all the materials be known. This was clearly not practical in terms of cost or time.
- 2 No air monitoring was carried out whilst the survey was undertaken and therefore care was taken not to cause disturbance of fibre or contamination of clean surfaces.
- 3 This report has been written with reference to the various Guidance Notes etc, issued, and current at the date of this report and describes circumstances at the site on the date the investigation took place.
- 4 Where similar items exist in the building, only one or two samples have been taken to ascertain the material content. It was assumed that similar products were of the same material. Only random sampling was carried
- Any person undertaking work within the buildings should be told of the presence of asbestos. This briefing 5 also applies to any other person associated with the site, including staff, sub-contractors and others.
- The diagrams in the report are not to scale and are illustrative only to indicate approximate locations. The 6 descriptions used are for location identification purposes
- 7 All the recommendations described in this report are based upon assumptions made after consideration of the type of material, condition of the material, its location, analysis result and type of use the area is thought to be subjected to. However, statutory authorities or others, could require amendments based on local knowledge, change in legislation, change in use or indeed, other conditions of criteria.
- Equipment, machinery, ducting etc were not moved, opened up or examined for the purpose of this 8 investigation except in the odd occasion where hatches were available.
- 9 It should be presumed that any firedoors contain asbestos unless otherwise indicated. It should also be presumed that structural firebreaks exist in the vicinity of a firedoor which are also likely to contain asbestos unless otherwise indicated. In the event of damage or exposure of fireproof material within any fire door, separate samples should be
- For further guidance on licenced and unlicenced work with Asbestos Containing Materials, the HSE website 10
- provides up to date information within the Asbestos Essentials section (www.hse.gov.uk/asbestos/essentials/).

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Survey Notes:	Page 1 of 1



taken and identified accordingly.

SECTION SEVEN

SURVEY SUMMARY

Survey Summary

- 1 For positive identification of asbestos bearing materials please refer to the individual sample data sheets.
- Due to the nature of usage of the buildings surveyed, sampling was restricted / limited in certain areas for both health and safety reasons and food hygiene reasons. Consequently where items are reported as suspected asbestos materials, these items should be treated as such until otherwise identified.
- All sample reference numbers and photograph reference numbers have been annotated on the accompanying plans, whether asbestos materials or not. This is for clarification where non-asbestos materials may be difficult to identify. However it must be stressed that if during refurbishment / maintenance work a suspect material is identified which is not included in this register, disturbance should be stopped prior to identification.
- This register has been compiled so as to allow information to be updated with relative ease. Any work involving the removal of asbestos materials identified within this register should be recorded and the information updated accordingly.
- Although work with asbestos cement does not necessarily require a licensed contractor it is recommended that all work involving the disturbance of any asbestos material is undertaken using contractors licensed by the HSE. Although asbestos cement is a relatively low risk material, it must not be interfered with in any way; e.g. cutting, drilling etc. as this may lead to raised airborne fibre levels. Where possible / practicable asbestos cement materials should be labelled appropriately. If asbestos cement materials are damaged or in areas where abrasion is likely, they should be encapsulated or removed.
- All Asbestos Insulation Board should be encapsulated and labelled. Where insulation board is likely to sustain damage it should be removed. All work involving the disturbance of Asbestos insulation board must be undertaken by a licensed contractor, this includes drilling, cutting, encapsulating etc. Where debris has been identified, access to the area should be restricted prior to decontamination or removal.

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Survey Summary:	Page 1 of 1





SECTION EIGHT

SURVEY RECOMMENDATIONS

Survey Recommendations

1 Material Assessment and Algorithm

The material assessment is an assessment of the condition of the ACM, or the presumed ACM, and the likelihood of it releasing fibres in the event of it being disturbed in some way. This material assessment will give a good initial guide to the priority for management, as it will identify the materials, which will most readily release airborne fibres if disturbed. However, there are other factors to take into account when prioritising action.

MDHS100 recommends the use of an algorithm to carry out the material assessment, and contains an example. The algorithm is a numerical way of taking into account several influencing factors, giving each factor considered a score. These scores can then be totaled to give a material assessment score. The use of algorithms is not infallible, but the assessment process is clear for all to see, so if discrepancies arise, it should be possible to track back through the assessment process to find the root of the error. The algorithm shown in MDHS100 considers four parameters that determine the risk from ACM: that is the ability to release fibres if disturbed. These four parameters are:

Product type; Extent of damage; Surface treatment; and Asbestos type

Each of the parameters is scored and added to give a total score between 2 and 12:

Materials with scores of 10 or more should be regarded as high risk with a significant potential to release fibres if disturbed;

Those with a score between 7 and 9 are regarded as medium risk;

Materials with a score between 5 and 6 are low risk; and

Scores of 4 or less are very low risk.

NADIS indicates a sample that having been analysed at the laboratory shows no sign of asbestos fibres being present within the sample (No Asbestos Discovered In Sample).

PRIORITY ASSESSMENT AND ALGORITHM

The material assessment identifies the high-risk materials, that is, those which will most readily release airborne fibres if disturbed. It does not automatically follow that those materials assigned the highest score in the material assessment will be the materials that should be given priority for remedial action. Management priority must be determined by carrying out a risk assessment which will also take into account factors such as:

Maintenance activity; Occupant activity; Likelihood of disturbance; Human exposure potential.

THE RISK ASSESSMENT INCLUDES A MATERIAL ASSESSMENT AND A PRIORITY ASSESSMENT.

THE MATERIAL ASSESSMENT LOOKS AT THE TYPE AND CONDITION OF THE ACM AND THE EASE

ſ	Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kno
			Survey Date:	09 August 2004
	Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
		Dorset, DT11 9JG	Recommendation:	Page 1 of 3



Survey Recommendations

WITH WHICH IT WILL RELEASE FIBRES IF DISTURBED.

THE PRIORITY ASSESSMENT LOOKS AT THE LIKELIHOOD OF SOMEONE DISTURBING THE ACM.

The risk assessment can only be carried out with detailed knowledge of all the above. Although a surveyor may have some of the information which will contribute to the risk assessment and may be part of an assessment team, you, as the duty holder under the Control of Asbestos Regulations 2006, are required to make the risk assessment, using the information given in the survey report and your detailed knowledge of the activities carried out within your premises. The risk assessment will form the basis of the management plan, so it is important that it is accurate.

If the use of the area or location changes, the risk assessment should be updated accordingly to reflect the change of use and potential for either increased or decreased exposure to fibres.

MAINTENANCE ACTIVITY

The first and most important factor which must be taken into consideration is the level of maintenance activity likely to be taking place in an area. Maintenance trades such as plumbers and electricians are the group who the duty to manage is primarily trying to protect. There are two types of maintenance activity, planned and unplanned. Planned work can be assessed and carried out using procedures and controls to reduce exposure to asbestos. Unplanned work requires the situation to be dealt with as found and the controls that can be applied may be more limited. The frequency of maintenance activities also need to be taken into account in deciding what management action is appropriate.

OCCUPANT ACTIVITY

The activities carried out in an area will have an impact on the risk assessment. When carrying out a risk assessment the main type of use of an area and the activities taking place within it should be taken into account. For example a little used storeroom or an attic will rarely be accessed and so any asbestos is unlikely to be disturbed. At the other end of the scale, in a warehouse lined with asbestos insulating board panels, with frequent vehicular movements, the potential for disturbance of ACMs is reasonably high and this would be a significant factor in the risk assessment. As well as the normal everyday activities taking place in an area, any secondary activities will need to be taken into account.

LIKELIHOOD OF DISTURBANCE

The two factors that will determine the likelihood of disturbance are the extent or amount of the ACM and its accessibility/vulnerability. For example, asbestos soffits outdoors are generally inaccessible without the use of ladders or scaffolding, are unlikely to be disturbed. The asbestos cement roof of a hospital ward is also unlikely to be disturbed, but its extent would need to be taken into account in any risk assessment. However if the same ward had asbestos panels on the walls they would be much more likely to be disturbed by trolley/bed movements.

HUMAN EXPOSURE POTENTIAL

The human exposure potential depends on three factors: the number of occupants of an area, the frequency of use of the area, and the average time each area is in use. For example, a school boiler room is likely to be unoccupied, but may be visited daily for a few minutes. The potential for exposure is much less than say in a classroom lined with asbestos insulating board panelling, which is occupied daily for six hours by 30 pupils and a teacher.

PRIORITY ASSESSMENT ALGORITHMS

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Recommendation:	Page 2 of 3





Survey Recommendations

Taking all these factors into account in a logical, consistent manner is difficult. Using an algorithm will help you to produce priority assessments that have taken the factors into account in a consistent way. The number of factors relevant at any one site needs to be carefully considered, as the more factors included in an algorithm, the lower the influence of the most important risk factors becomes, and this may produce anomalies. For this reason it is recommended that the number of factors that are scored is limited to four, the same as the number of factors in the material assessment. There is no single set of factors that can be recommended that will apply equally to all types of premises. Therefore four general headings have been used and one or more factors can be taken into account and averaged under each heading to suit the circumstances. If you choose to use more than one factor under a general heading, then average the scores under that heading, rounding up where necessary.

The scores from the material assessment (i.e. the condition of the ACM or presumed ACM) are added to the scores of the priority assessment (the likelihood of disturbance), to give the overall risk assessment. Risk assessment scores for different ACMs can then be compared to develop your action plan. In many circumstances the scores will be similar, making decisions more difficult. For example a boiler house with asbestos pipe work insulation in poor condition may get the same or similar risk assessment score to an office with asbestos insulating board in reasonably good condition. This is simply because the ACM in the boiler house received a higher score than the ACM in the office because the ACM in the boiler house was in poor condition. However, the priority assessment for the office will get a higher score than the boiler house since the office is occupied more often. Add the scores together for the material and priority assessments, and you get similar scores. If this is the case then you may decide that the office needs doing first because it is used daily. On the other hand you may decide that the poor condition of the ACM in the boiler house means that it should be done first. If the office was a classroom, the young age of the occupants may be a deciding factor. Algorithms are provided to help you, but they are best guesses and will often require you to make your own additional judgements.

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address:	True Lovers Knot, Tarrant Keyneston, Blandford,	Printed On:	01 November 2008
	Dorset, DT11 9JG	Recommendation:	Page 3 of 3





SECTION NINE

MATERIAL ASSESSMENT: SUMMARY BY AREA

Material Assessment: Summary by Area

Site Name:

Project Number:

True Lovers Knot

AS04121 - True Lovers Knot

Area: Not Applicable

Sample Date	Location Ref	Location ID	Drawing Reference	Floor	Room	Asbestos Type	Product Name	Material Risk Score	Material Risk Band	Priority Risk Score	Comments	Action	Survey Type
09/08/04	14	521	14	External grd floor	Roof	Chrysotile	Roofing felt	2	Very Low Risk	3		No Action Required	T 2
09/08/04	11	518	11	First floor	Corridor	Chrysotile	Fuse & Switchgear Flashguard	3	Very Low Risk	3		Apply Warning Labels	T 2
09/08/04	12	519	12	First floor	Lounge & dining room	Not Applicable	Hatch	0	Not Applicable	2	The above the hatch was inaccesible during the survey and consequently ACM's must be presumed to be present until proved otherwise.	No Action Required	T 2
09/08/04	3	510	3 and other locations	Ground floor	All	Chrysotile	Fire Door	3	Very Low Risk	4		Apply Warning Labels	T 2
09/08/04	6	513	6	Ground floor	Boiler cupboard	NADIS	Cladding	0	NADIS	N/A		No Action Required	T 2
09/08/04	7	514	7	Ground floor	Boiler cupboard	Chrysotile	Boiler	3	Very Low Risk	4		Apply Warning Labels	T 2
09/08/04	8	515	8	Ground floor	Boiler cupboard	Chrysotile	Flue	3	Very Low Risk	5		Apply Warning Labels	T 2
09/08/04	10	517	10	Ground floor	Electrical cupboard	Chrysotile	Fuse & Switchgear Flashguard	3	Very Low Risk	3		Apply Warning Labels	T 2
09/08/04	4	511	4	Ground floor	Lobby	NADIS	Wall	0	NADIS	N/A		No Action Required	T 2
09/08/04	5	512	5	Ground floor	Staircase	Chrysotile	Cladding	3	Very Low Risk	5		Apply Warning Labels	T 2
09/08/04	9	516	9	Ground floor	Store Room	NADIS	Ceiling	0	NADIS	N/A	This ceiling material is identical to the wall material in location 4.	No Action Required	T 2

Material Assessment: Summary by Area

Site Name:

True Lovers Knot

Project Number:

AS04121 - True Lovers Knot

Not Applicable Area:

Sample Date	Location Ref	Location ID	Drawing Reference	Floor	Room	Asbestos Type	Product Name	Material Risk Score	Material Risk Band	Priority Risk Score	Comments	Action	Survey Type
09/08/04	1	508	1	Ground floor	WC - ladies	Chrysotile	Debris	6	Low Risk	4	This material has been left after previous work and is accessible via the hatch into the ceiling. Warning labels should be applied immediately and the debris should be removed as soon as practicable.	Removal	Т2
09/08/04	2	509	2	Ground floor	WC - ladies	Chrysotile	Cistern	2	Very Low Risk	4		Apply Warning Labels	T 2
09/08/04	13	520	13	Ground floor	WC - mens	Chrysotile	Cistern	2	Very Low Risk	3		Apply Warning Labels	T 2
09/08/04	15	522	15	Second floor	Roof	Chrysotile	Roofing felt	2	Very Low Risk	1		No Action Required	T 2

SECTION TEN

MATERIAL ASSESSMENT (PHOTO)

Material Assessment Record

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, Site Address: DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID:	508	Survey Type:	T 2
Location Ref:	1	Product Type:	Asbestos cement
Product:	Debris	Damage:	High damage
Area:	Not Applicable	Treatment:	Asbestos cement sheets etc
Floor:	Ground floor	Asbestos Type:	Chrysotile
Room:	WC - ladies	Identification:	Identified
Surveyor Name:	J D Chilvers	Quantity:	
Drawing Ref:	1	Accessibility:	Medium Accessibility
Asbestos ?	Yes		
Date:	09 August 2004		Material Risk Score 6
Next Inspection:	08 February 2005		Material Risk Band: Low Risk
	,		Priority Risk Score: 4



Material Comments:

Action:

This material has been left after previous work and is accessible via the hatch into the ceiling. Warning labels should be applied immediately and the debris should be removed as soon as practicable.

Removal

Material Assessment Record

Action:

Hall & Woodhouse Ltd Client Name: Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG Project Number: AS04121 - True Lovers Knot T 2 Location ID: 509 Survey Type: Location Ref: 2 **Product Type: Plastics** Product: Cistern Damage: No visible damage Not Applicable Treatment: Reinforced plastics Area: Ground floor Chrysotile Floor: Asbestos Type: WC - ladies Identification: Strongly Presumed Room: J D Chilvers Surveyor Name: Quantity: 2 Easy Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 2 09 August 2004 Date: Material Risk Band: Very Low Risk Next Inspection: 09 August 2005 Priority Risk Score:



Apply Warning Labels

Material Comments:

Material Assessment Record

Action:

Hall & Woodhouse Ltd Client Name: Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG Project Number: AS04121 - True Lovers Knot T 2 Location ID: 510 Survey Type: Location Ref: 3 **Product Type:** Asbestos cement Product: Fire Door Damage: No visible damage Not Applicable Treatment: Asbestos cement sheets etc Area: Ground floor Chrysotile Floor: Asbestos Type: All Identification: Presumed Room: J D Chilvers Surveyor Name: Quantity: 3 and other locations Medium Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 3 09 August 2004 Date: Material Risk Band: Very Low Risk Next Inspection: 09 August 2005 Priority Risk Score:



Apply Warning Labels

Material Comments:

Material Assessment Record

Action:

			Client Name:	Hall & Woo	odhouse Ltd	
	ue Lovers Knot, Tarrant Keyneston, Blandford, Do 11 9JG	orset,				
		F	Project Number:	AS04121 - Tr	ue Lovers Knot	
Location ID:	511	Survey Type:		T 2		
Location Ref:	4	Product Type:		NADIS		
Product:	Wall	Damage:		NADIS		
Area:	Not Applicable	Treatment:		NADIS		
Floor:	Ground floor	Asbestos Typ	e:	NADIS		
Room:	Lobby	Identification:		Identified		
Surveyor Name:	J D Chilvers	Quantity:				
Drawing Ref:	4	Accessibility:				
Asbestos ?	No					
Date:	09 August 2004		Materia	al Risk Score	0	
Next Inspection:	Not Applicable		Materia	al Risk Band:	NADIS	
. iosti inspositorii	• •		Priority	Risk Score:	N/A	



No Action Required

Material Comments:	

Material Assessment Record

Action:

Hall & Woodhouse Ltd Client Name: Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG Project Number: AS04121 - True Lovers Knot T 2 Location ID: 512 Survey Type: Location Ref: 5 **Product Type:** Asbestos cement Product: Cladding Damage: No visible damage Not Applicable Treatment: Asbestos cement sheets etc Area: Ground floor Chrysotile Floor: Asbestos Type: Staircase Identification: Presumed Room: J D Chilvers Surveyor Name: Quantity: 5 Easy Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 3 09 August 2004 Date: Material Risk Band: Very Low Risk Next Inspection: 09 August 2005 Priority Risk Score: 5



Apply Warning Labels

Material Comments:

Material Assessment Record

Action:

	True Lovers Knot, Tarrant Keyneston, Blandford,	Dorset,	Client Name:		Hall & Woodhouse Ltd	
	3111 930		Projec	t Number:	AS04121 - Tru	e Lovers Knot
Location ID:	513	Survey Ty	pe:		T 2	
Location Ref:	6	Product Ty	/pe:		NADIS	
Product:	Cladding	Damage:			NADIS	
Area:	Not Applicable	Treatment	:		NADIS	
Floor:	Ground floor	Asbestos	Гуре:		NADIS	
Room:	Boiler cupboard	Identificati	on:		Identified	
Surveyor Name	e: J D Chilvers	Quantity:				
Drawing Ref:	6	Accessibil	ty:			
Asbestos ?	No					
Date:	09 August 2004				Risk Score	0
Next Inspection	Not Applicable	_]		Materia	Risk Band:	NADIS
•		_		Priority	Risk Score:	N/A



No Action Required

Material Comments:		

Material Assessment Record

Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset,

DT11 9JG

Date:

Next Inspection:

Client Name: Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID:	514	Survey Type:	T 2
Location Ref:	7	Product Type:	Gaskets
Product:	Boiler	Damage:	No visible damage
Area:	Not Applicable	Treatment:	Composite asbestos materials
Floor:	Ground floor	Asbestos Type:	Chrysotile
Room:	Boiler cupboard	Identification:	Presumed
Surveyor Name:	J D Chilvers	Quantity:	
Drawing Ref:	7	Accessibility:	Medium Accessibility
Ashestos ?	Yes]	

09 August 2004 Material Risk Band: Very Low Risk 09 August 2005

Priority Risk Score:

Material Risk Score

Action: Apply Warning Labels



Material Comments:

Material Assessment Record

Client Name: Hall & Woodhouse Ltd Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG Project Number: AS04121 - True Lovers Knot Survey Type: T 2 Location ID: 515 Location Ref: 8 **Product Type:** Asbestos cement Product: Flue Damage: No visible damage Not Applicable Treatment: Asbestos cement sheets etc Area: Ground floor Chrysotile Floor: Asbestos Type: Boiler cupboard Strongly Presumed Identification: Room: J D Chilvers Surveyor Name: Quantity: Medium Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 3 09 August 2004 Date: Material Risk Band: Very Low Risk Next Inspection: 09 August 2005





Material Comments:	

5

Priority Risk Score:

Material Assessment Record

Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Hall & Woodhouse Ltd Client Name:

Project Number: AS04121 - True Lovers Knot

T 2 Location ID: 516 Survey Type: Location Ref: 9 **Product Type: NADIS** Product: Ceiling Damage: **NADIS** Not Applicable Treatment: **NADIS** Area: Ground floor NADIS Floor: Asbestos Type: Store Room Identified Identification: Room: J D Chilvers Surveyor Name: Quantity: Drawing Ref: Accessibility: Asbestos? No

Material Risk Score 0 Material Risk Band: **NADIS** Priority Risk Score: N/A

Action: No Action Required

09 August 2004

Not Applicable



Material Comments:

Date:

Next Inspection:

This ceiling material is identical to the wall material in location 4.

Material Assessment Record

Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset,

DT11 9JG

Asbestos?

Next Inspection:

Date:

Client Name: Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID:	517	Survey Type:	T 2
Location Ref:	10	Product Type:	Ropes and woven textiles
Product:	Fuse & Switchgear Flashguard	Damage:	No visible damage
Area:	Not Applicable	Treatment:	Composite asbestos materials
Floor:	Ground floor	Asbestos Type:	Chrysotile
Room:	Electrical cupboard	Identification:	Presumed
Surveyor Name:	J D Chilvers	Quantity:	
Drawing Ref:	10	Accessibility:	Medium Accessibility

Material Risk Score 3 Material Risk Band: Very Low Risk Priority Risk Score:

Action: Apply Warning Labels

Yes

09 August 2004

09 August 2005



Material Comments:

Material Assessment Record

Asbestos?

Next Inspection:

Date:

Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset,

DT11 9JG

Client Name: Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID:	518	Survey Type:	T 2
Location Ref:	11	Product Type:	Ropes and woven textiles
Product:	Fuse & Switchgear Flashguard	Damage:	No visible damage
Area:	Not Applicable	Treatment:	Composite asbestos materials
Floor:	First floor	Asbestos Type:	Chrysotile
Room:	Corridor	Identification:	Presumed
Surveyor Name:	J D Chilvers	Quantity:	
Drawing Ref:	11	Accessibility:	Medium Accessibility

Material Risk Score 3 Material Risk Band: Very Low Risk Priority Risk Score:

Action: Apply Warning Labels

Yes

09 August 2004

09 August 2005



Material Comments:

Material Assessment Record

	rue Lovers Knot, Tarrant Keyneston, Blandford, Dor	rset,	Client Name:	lient Name: Hall & Woodhouse Ltd		
	DT11 9JG				True Lovers Knot	
Location ID:	519	Survey Typ	e:	T 2		
Location Ref:		Product Typ		Not Applicable		
Product:		Damage:		Not Applicable		
Area:	Not Applicable	Treatment:		Not Applicable		
Floor:	First floor	Asbestos Ty	/pe:	Not Applicable		
Room:	Lounge & dining room	Identificatio	n:	Strongly Presume	ed	
Surveyor Name	J D Chilvers	Quantity:				
Drawing Ref:	12	Accessibility	/ :	Medium Accessib	ility	
Asbestos ?	No					
Date:	09 August 2004			erial Risk Score	0	
Next Inspection	Not Applicable			erial Risk Band:	Not Applicable	
			Piloi	rity Risk Score:	2	
Action:		No Action	n Required			
	No Pictu	ıre Avail	able			
Material Comments:	The above the hatch was inaccesible during the		nsequently ACM's mus rwise.	t be presumed to be	present until proved	

Material Assessment Record

Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset,

DT11 9JG

Asbestos?

Next Inspection:

Date:

Client Name: Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID:	520	Survey Type:	T 2
Location Ref:	13	Product Type:	Plastics
Product:	Cistern	Damage:	No visible damage
Area:	Not Applicable	Treatment:	Reinforced plastics
Floor:	Ground floor	Asbestos Type:	Chrysotile
Room:	WC - mens	Identification:	Strongly Presumed
Surveyor Name:	J D Chilvers	Quantity:	
Drawing Ref:	13	Accessibility:	Medium Accessibility

Material Risk Score Material Risk Band: Very Low Risk Priority Risk Score:

Action: Apply Warning Labels

Yes

09 August 2004

09 August 2005



Material Comments:

Material Assessment Record

Action:

Hall & Woodhouse Ltd Client Name: Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG Project Number: AS04121 - True Lovers Knot T 2 Location ID: 521 Survey Type: Location Ref: 14 **Product Type:** Roofing felts Product: Roofing felt Damage: No visible damage Not Applicable Treatment: Resins Area: External grd floor Chrysotile Floor: Asbestos Type: Roof Identification: Presumed Room: J D Chilvers Surveyor Name: Quantity: 14 Medium Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 2 09 August 2004 Date: Material Risk Band: Very Low Risk Next Inspection: 09 August 2005 Priority Risk Score:



No Action Required

Material Comments:

Material Assessment Record

Action:

Client Name: Hall & Woodhouse Ltd Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG Project Number: AS04121 - True Lovers Knot Survey Type: T 2 Location ID: 522 Location Ref: 15 **Product Type:** Roofing felts Product: Roofing felt Damage: No visible damage Not Applicable Treatment: Resins Area: Second floor Chrysotile Floor: Asbestos Type: Roof Identification: Presumed Room: J D Chilvers Surveyor Name: Quantity: 15 Medium Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 09 August 2004 Date: Material Risk Band: Very Low Risk Next Inspection: 09 August 2005 Priority Risk Score:



No Action Required

Material Comments:	

SECTION ELEVEN

BULK IDENTIFICATION REPORT

BULK IDENTIFICATION REPORT

Client:	Hall & Woodhouse Ltd	Date Samples	09/08/2004
		Received:	
Client	The Brewery, Blandford St Mary, Dorset, DT11 9LS	Date Samples	16/08/2004
Address:		Analysed:	
Site	True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG		
Address:			
F.A.O:	James Overy		Page 1 of 1

METHOD USED:

Samples of material referenced below, have been examined to determine the presence of asbestos fibres, using a method of polarising light microscopy and centre stop dispersion staining, based on H.S.E,s MDHS 77. NOTE: We cannot be held responsib for the accuracy and competence of samples taken by third parties. Under these circumstances we cannot be held responsible for the interpretation of the results shown.

	Location ID	Sample Location	Fibre Type
1	508	Ground floor, WC - ladies, Debris	Chrysotile
4	511	Ground floor, Lobby, Wall	NADIS
6	513	Ground floor, Boiler cupboard, Cladding	NADIS
9	516	Ground floor, Store Room, Ceiling	NADIS

REPORT RAISED BY:	
Signed:	Print:



SECTION TWELVE

PRIORITY ASSESSMENT: SUMMARY BY AREA

Priority Assessment: Summary by Area

Site Name:

True Lovers Knot

Project Number:

AS04121 - True Lovers Knot

Not Applicable Area:

Sample Date	Location Ref	Location ID	Drawing Reference	Floor	Room	Comments	Normal Occupant Activity	Likelihood Of Disturbance	Human Exposure Potential	Maintenance Activity	Risk Score
09/08/04	14	521	14	External grd floor	Roof		0	1	1	1	3
09/08/04	11	518	11	First floor	Corridor		0	1	1	1	3
09/08/04	12	519	12	First floor	Lounge & dining room		0	1	0	1	2
09/08/04	3	510	3 and other locations	Ground floor	All		1	1	1	1	4
09/08/04	7	514	7	Ground floor	Boiler cupboard		1	1	1	1	4
09/08/04	8	515	8	Ground floor	Boiler cupboard		1	2	1	1	5
09/08/04	10	517	10	Ground floor	Electrical cupboard		0	1	1	1	3
09/08/04	5	512	5	Ground floor	Staircase		1	1	2	1	5
09/08/04	1	508	1	Ground floor	WC - ladies	This material is contained within the loft space above the ladies wc. Any person accessing this area should take the appropriate precautions and wear PPE.	0	2	0	2	4
09/08/04	2	509	2	Ground floor	WC - ladies		1	1	1	1	4
09/08/04	13	520	13	Ground floor	WC - mens		0	1	1	1	3
09/08/04	15	522	15	Second floor	Roof		0	0	0	1	1

SECTION THIRTEEN

PRIORITY ASSESSMENT RECORD

Priority Assessment Record

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 508 Location Ref: Debris Product: Not Applicable Area: Ground floor Floor: WC - ladies Room: J D Chilvers Surveyor Name: Drawing Ref: 1 Yes Asbestos? 09 August 2004 Date:

09.007-1002

Priority Comments:

This material is contained within the loft space above the ladies wc. Any person accessing this area should take the appropriate precautions and wear PPE.

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Confined spaces	3	
Accessibility:	Easily disturbed	2	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	2
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Infrequent	0	average
Average time area is in use:	<1 hour	0	0
Maintenance Activity:			
Type of maintenance activity:	Low disturbance	1	average
Frequency of maintenance activity	>1 per year	2	2

Total Priority Assessment Score:		
Material Assessment Score (supplied by surveyor):	Low Risk	6
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 1 of 1



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 509 2 Location Ref: Cistern Product: Not Applicable Area: Ground floor Floor: WC - ladies Room: J D Chilvers Surveyor Name: 2 Drawing Ref: Asbestos? Yes Date: 09 August 2004 09/08/2004

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Low disturbance	1	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		
Material Assessment Score (supplied by surveyor):	Very Low Risk	2
Total of Material and Priority Assessment Scores:		6

Priority Assessment: Page 2 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 510 3 Location Ref: Fire Door Product: Not Applicable Area: Ground floor Floor: Room: ΑII J D Chilvers Surveyor Name: Drawing Ref: 3 and other locations Asbestos? Yes Date: 09 August 2004

09/08/2004

Priority Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Low disturbance	1	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		4
Material Assessment Score (supplied by surveyor):	Very Low Risk	3
Total of Material and Priority Assessment Scores:		7

Priority Assessment: Page 3 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 512 5 Location Ref: Cladding Product: Not Applicable Area: Ground floor Floor: Staircase Room: J D Chilvers Surveyor Name: 5 Drawing Ref: Asbestos? Yes Date: 09 August 2004



Priority Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>3 to <6 hours	2	2
Maintenance Activity:			
Type of maintenance activity:	Low disturbance	1	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Very Low Risk	3
Total of Material and Priority Assessment Scores:		8

Priority Assessment: Page 4 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 514 7 Location Ref: Boiler Product: Not Applicable Area: Ground floor Floor: Boiler cupboard Room: J D Chilvers Surveyor Name: 7 Drawing Ref: Asbestos? Yes Date: 09 August 2004

09 88 /2002

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Confined spaces	3	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Weekly	2	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:	
Material Assessment Score (supplied by surveyor): Very Low Risk	3
Total of Material and Priority Assessment Scores:	7

Priority Assessment: Page 5 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 515 8 Location Ref: Flue Product: Not Applicable Area: Ground floor Floor: Boiler cupboard Room: J D Chilvers Surveyor Name: 8 Drawing Ref: Asbestos? Yes Date: 09 August 2004

\$705.92004

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Confined spaces	3	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	2
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Weekly	2	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Very Low Risk	3
Total of Material and Priority Assessment Scores:		8

Priority Assessment: Page 6 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 517 10 Location Ref: Fuse & Switchgear Flashguard Product: Not Applicable Area: Ground floor Floor: Electrical cupboard Room: J D Chilvers Surveyor Name: 10 Drawing Ref: Asbestos? Yes Date: 09 August 2004

09/08/2004

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Low disturbance	1	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		3
Material Assessment Score (supplied by surveyor): Very Low Risk		3
Total of Material and Priority Assessment Scores:		6

Priority Assessment: Page 7 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 518 11 Location Ref: Fuse & Switchgear Flashguard Product: Not Applicable Area: First floor Floor: Corridor Room: J D Chilvers Surveyor Name: 11 Drawing Ref: Asbestos? Yes 09 August 2004 Date:

09/08/2004

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Confined spaces	3	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Weekly	2	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		3
Material Assessment Score (supplied by surveyor): Very Low Risk		3
Total of Material and Priority Assessment Scores:		6

Priority Assessment: Page 8 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID:	519		
Location Ref:	12		
Product:	Hatch		
Area:	Not Applicable		No Picture Available
Floor:	First floor		
Room:	Lounge & dining room		
Surveyor Name:	J D Chilvers		
Drawing Ref:	12	Priority	
Asbestos ?	No	Comments:	
Date:	09 August 2004		

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Confined spaces	3	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Infrequent	0	average
Average time area is in use:	<1 hour	0	0
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		2
Material Assessment Score (supplied by surveyor):	Not Applicable	0
Total of Material and Priority Assessment Scores:		2

Priority Assessment: Page 9 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 520 13 Location Ref: Cistern Product: Not Applicable Area: Ground floor Floor: WC - mens Room: J D Chilvers Surveyor Name: 13 Drawing Ref: Asbestos? Yes 09 August 2004 Date:

09/08/2004

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		3
Material Assessment Score (supplied by surveyor):	Very Low Risk	2
Total of Material and Priority Assessment Scores:		5

Priority Assessment: Page 10 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 521 14 Location Ref: Roofing felt Product: Not Applicable Area: External grd floor Floor: Room: Roof J D Chilvers Surveyor Name: 14 Drawing Ref: Asbestos? Yes Date: 09 August 2004

TO LET POR 1 09 7 08 / 2004

Priority Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Outdoors	0	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	>10 to <=50 (m2 or pipe run)	2	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		3
Material Assessment Score (supplied by surveyor):	Very Low Risk	2
Total of Material and Priority Assessment Scores:		5

Priority Assessment: Page 11 of 1.



Priority Assessment Record

Site Address:

True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS04121 - True Lovers Knot

Location ID: 522 15 Location Ref: Roofing felt Product: Not Applicable Area: Second floor Floor: Room: Roof J D Chilvers Surveyor Name: 15 Drawing Ref: Asbestos? Yes Date: 09 August 2004 09/08/2004

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Outdoors	0	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	0
Human Exposure Potential:			
Number of occupants:	None	0	
Frequency of use of area:	Infrequent	0	average
Average time area is in use:	<1 hour	0	0
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		1
Material Assessment Score (supplied by surveyor):	Very Low Risk	2
Total of Material and Priority Assessment Scores:		3

Priority Assessment: Page 12 of 1.



SECTION FOURTEEN

EXCLUDED AREAS

Excluded Areas

The hatch in the sitting room on the first floor was inaccessible and so it must be presumed that ACM's (asbestos containing materials) are present until proven otherwise.

Client Name:	Hall & Woodhouse Ltd	Project Number:	S04121 - True Lovers Kn
		Survey Date:	09 August 2004
Site Address: True Lovers Knot, Tarrant Keyneston, Blandford, Dorset, DT11 9JG		Printed On:	01 November 2008
		Excluded Areas:	Page 1 of 1

