Asbestos Survey for

Hall & Woodhouse Ltd

at

Norfolk Arms
Crawley Road
Roffey
Horsham
West Sussex
RH12 4NB



Project Number: AS07220 - Norfolk Arms

Printed: 19/12/2007 By: JTEC Environmental Ltd.. Using Multibase software.



Names and Addresses

<u>Client Name:</u> <u>Instructing Party:</u>

Hall & Woodhouse Ltd Hall & Woodhouse Ltd

The Brewery The Brewery

Blandford St Mary Blandford St Mary

Dorset DT11 9LS DT11 9LS

Contact: Contact:

Phone: 01258 452141 Fax: Phone: 01258 452141 Fax:

<u>Site Full Name:</u> <u>Report Author:</u>

Norfolk Arms JTEC Environmental Ltd.

Crawley Road Tansley Cottage, Shave Lane,

Roffey Todber,

Horsham Sturminster Newton,

West Sussex Dorset.

RH12 4NB DT10 1JA

Contact: Contact: John Chilvers

Phone: Fax: Surveyor

ne: Fax: Surveyor

Phone: 01258 821398 Fax: 01258 821398

JTEC Environmental Ltd.

Project Number: AS07220 - Norfolk Arms
Survey Date: 05 December 2007
Printed On: 19 December 2007
Page: Page 1 of 1



TABLE OF CONTENTS

SECTION	1	Site Description
SECTION	2	Survey Drawings
SECTION	3	Survey Objectives
SECTION	4	Survey Techniques
SECTION	5	Survey Caveat
SECTION	6	Survey Notes
SECTION	7	Survey Summary
SECTION	8	Survey Recommendations
SECTION	9	Material Assessment: Summary by Area
SECTION	10	Material Assessment (Photo)
SECTION	11	Bulk Identification Report
SECTION	12	Priority Assessment: Summary by Area
SECTION	13	Priority Assessment (Photo)
SECTION	14	Excluded Areas



SECTION ONE

SITE DESCRIPTION

Site Description

General Information:

This building is estimated to be c.100 years old. It is of brick construction and has a basement cellar. The building has been substantially altered within the last 15 years or so.

ACMs (asbestos containing materials) have been confirmed around the boiler room area and they may exist around structural beams underneath the exterior cladding.

Area	Comments	Accessed
Main building - basement and ground floor	Samples taken & presumed asbestos materials present, asbestos materials present in samples.	Yes

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms
		Survey Date:	05 December 2007
Site Address:	Norfolk Arms. Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007
	Sussex, RH12 4NB	Site Description:	Page 1 of 1




SECTION TWO

SURVEY DRAWINGS




Survey Drawings and Documentation

Project Number: AS07220 - Norfolk Arms



BASEMENT



GROUND FLOOR

Description of Drawing:

Site layout

SECTION THREE

SURVEY OBJECTIVES

Survey Objectives

- Produce a report, in a database format, indicating areas containing identified and suspected asbestos based materials, including photographic records of asbestos occurences where possible.
- 2 To carry out a survey to ascertain the presence of asbestos based materials.
- 3 To include a risk assessment for each individual Sample.

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms
		Survey Date:	05 December 2007
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007
	Sussex, RH12 4NB	Survey Objectives:	Page 1 of 1





SECTION FOUR

SURVEY TECHNIQUE

Survey Technique

- 1 Materials of a similar type were only occasionally sampled and it was assumed that other surfaces identical to where the sample was taken, was of a similar composition.
- 2 Photographs were taken at all of the sample locations (unless otherwise stated).
- 3 Samples were returned to the Main Laboratory for analysis.
- Asbestos Bulk Sample Analysis is conducted by using Polarised Light and Dispersion Staining Techniques. Dispersion Staining is used to describe the colour effects produced when a transparent colourless particle or fibre is immersed in a liquid having a refractive index near to that of the particle or fibre, and is viewed under a microscope using transmitted white light (based on HSE Publication MDHS 77).

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms
		Survey Date:	05 December 2007
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007
	Sussex, RH12 4NB	Survey Technique:	Page 1 of 1





SECTION FIVE

SURVEY CAVEAT

Survey Caveat

- This report is based upon a non-destructive inspection of an unfamiliar site. During the course of the survey all reasonable efforts were made to identify the physical presence of materials containing asbestos within the areas of the building which are subject to future refurbishment works. It is known that asbestos materials are frequently concealed within the fabric of buildings or within sealed building voids so that it is not possible to regard the findings of any survey as being definitive. It must always remain a possibility that further asbestos containing materials may be found during refurbishment or demolition activities. For reasons set out in this report, the results cannot give an assurance that all asbestos materials have been found and must not be thought to do so. The nature of the survey was a non-destructive inspection at key locations of accessible voids and areas. From the evidence of the inspections and of the sampling and analysis undertaken, it is clear that asbestos containing materials are either present or within or associated with various areas as detailed in the report. We recommend that samples be taken of suspect materials which may be uncovered within the listed areas or within the areas of the site which were not included in this survey.
- From mid 2005, sample analysing laboratories do not provide information on the amounts of asbestos fibre present within materials as their UKAS or equivalent accreditation does not permit this. Therefore any reference to the concentrations of fibres that appear in any survey report are only approximations and are intended for guidance only.

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms		
		Survey Date:	05 December 2007		
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007		
	Sussex, RH12 4NB	Survey Caveat:	Page 1 of 1		

Printed: 19/12/2007 By: JTEC Environmental Ltd.. Using Multibase software.



SECTION SIX

SURVEY NOTES

Survey Notes

- Whilst every effort was made to locate the ceiling panels, wall partitions and other panels, which may have been constructed from asbestos boarding, none other than those detailed were found. Some may have been missed due to repairs, alterations etc, where false and other finishes have been applied or where different specifications (including a possible mixture of asbestos and non-asbestos) panels have been used in the same area. Only by sampling each panel would the composition of all the materials be known. This was clearly not practical in terms of cost or time.
- 2 No air monitoring was carried out whilst the survey was undertaken and therefore care was taken not to cause disturbance of fibre or contamination of clean surfaces.
- 3 This report has been written with reference to the various Guidance Notes etc, issued, and current at the date of this report and describes circumstances at the site on the date the investigation took place.
- Where similar items exist in the building, only one or two samples have been taken to ascertain the material content. It was assumed that similar products were of the same material. Only random sampling was carried out.
- Any person undertaking work within the buildings should be told of the presence of asbestos. This briefing also applies to any other person associated with the site, including staff, sub-contractors and others.
- The diagrams in the report are not to scale and are illustrative only to indicate approximate locations. The descriptions used are for location identification purposes
- All the recommendations described in this report are based upon assumptions made after consideration of the type of material, condition of the material, its location, analysis result and type of use the area is thought to be subjected to. However, statutory authorities or others, could require amendments based on local knowledge, change in legislation, change in use or indeed, other conditions of criteria.
- 8 Equipment, machinery, ducting etc were not moved, opened up or examined for the purpose of this investigation except in the odd occasion where hatches were available.
- It should be presumed that any firedoors contain asbestos unless otherwise indicated. It should also be presumed that structural firebreaks exist in the vicinity of a firedoor which are also likely to contain asbestos unless otherwise indicated.
 - In the event of damage or exposure of fireproof material within any fire door, separate samples should be taken and identified accordingly.

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms		
		Survey Date:	05 December 2007		
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007		
	Sussex, RH12 4NB	Survey Notes:	Page 1 of 1		





SECTION SEVEN

SURVEY SUMMARY

Survey Summary

- 1 For positive identification of asbestos bearing materials please refer to the individual sample data sheets.
- Due to the nature of usage of the buildings surveyed, sampling was restricted / limited in certain areas for both health and safety reasons and food hygiene reasons. Consequently where items are reported as suspected asbestos materials, these items should be treated as such until otherwise identified.
- All sample reference numbers and photograph reference numbers have been annotated on the accompanying plans, whether asbestos materials or not. This is for clarification where non-asbestos materials may be difficult to identify. However it must be stressed that if during refurbishment / maintenance work a suspect material is identified which is not included in this register, disturbance should be stopped prior to identification.
- This register has been compiled so as to allow information to be updated with relative ease. Any work involving the removal of asbestos materials identified within this register should be recorded and the information updated accordingly.
- Although work with asbestos cement does not necessarily require a licensed contractor it is recommended that all work involving the disturbance of any asbestos material is undertaken using contractors licensed by the HSE. Although asbestos cement is a relatively low risk material, it must not be interfered with in any way; e.g. cutting, drilling etc. as this may lead to raised airborne fibre levels. Where possible / practicable asbestos cement materials should be labelled appropriately. If asbestos cement materials are damaged or in areas where abrasion is likely, they should be encapsulated or removed.
- All Asbestos Insulation Board should be encapsulated and labelled. Where insulation board is likely to sustain damage it should be removed. All work involving the disturbance of Asbestos insulation board must be undertaken by a licensed contractor, this includes drilling, cutting, encapsulating etc. Where debris has been identified, access to the area should be restricted prior to decontamination or removal.

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms
		Survey Date:	05 December 2007
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007
	Sussex, RH12 4NB	Survey Summary:	Page 1 of 1

Printed: 19/12/2007 By: JTEC Environmental Ltd.. Using Multibase software.



SECTION EIGHT

SURVEY RECOMMENDATIONS

Survey Recommendations

1 Material Assessment and Algorithm

The material assessment is an assessment of the condition of the ACM, or the presumed ACM, and the likelihood of it releasing fibres in the event of it being disturbed in some way. This material assessment will give a good initial guide to the priority for management, as it will identify the materials, which will most readily release airborne fibres if disturbed. However, there are other factors to take into account when prioritising action.

MDHS100 recommends the use of an algorithm to carry out the material assessment, and contains an example. The algorithm is a numerical way of taking into account several influencing factors, giving each factor considered a score. These scores can then be totaled to give a material assessment score. The use of algorithms is not infallible, but the assessment process is clear for all to see, so if discrepancies arise, it should be possible to track back through the assessment process to find the root of the error. The algorithm shown in MDHS100 considers four parameters that determine the risk from ACM: that is the ability to release fibres if disturbed. These four parameters are:

Product type; Extent of damage; Surface treatment; and Asbestos type

Each of the parameters is scored and added to give a total score between 2 and 12:

Materials with scores of 10 or more should be regarded as high risk with a significant potential to release fibres if disturbed;

Those with a score between 7 and 9 are regarded as medium risk;

Materials with a score between 5 and 6 are low risk; and

Scores of 4 or less are very low risk.

NADIS indicates a sample that having been analysed at the laboratory shows no sign of asbestos fibres being present within the sample (No Asbestos Discovered In Sample).

PRIORITY ASSESSMENT AND ALGORITHM

The material assessment identifies the high-risk materials, that is, those which will most readily release airborne fibres if disturbed. It does not automatically follow that those materials assigned the highest score in the material assessment will be the materials that should be given priority for remedial action. Management priority must be determined by carrying out a risk assessment which will also take into account factors such as:

Maintenance activity; Occupant activity; Likelihood of disturbance; Human exposure potential.

THE RISK ASSESSMENT INCLUDES A MATERIAL ASSESSMENT AND A PRIORITY ASSESSMENT.

THE MATERIAL ASSESSMENT LOOKS AT THE TYPE AND CONDITION OF THE ACM AND THE EASE

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms
		Survey Date:	05 December 2007
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007
	Sussex, RH12 4NB	Recommendation:	Page 1 of 3





Survey Recommendations

WITH WHICH IT WILL RELEASE FIBRES IF DISTURBED.

THE PRIORITY ASSESSMENT LOOKS AT THE LIKELIHOOD OF SOMEONE DISTURBING THE ACM.

The risk assessment can only be carried out with detailed knowledge of all the above. Although a surveyor may have some of the information which will contribute to the risk assessment and may be part of an assessment team, you, as the duty holder under the Control of Asbestos Regulations 2006, are required to make the risk assessment, using the information given in the survey report and your detailed knowledge of the activities carried out within your premises. The risk assessment will form the basis of the management plan, so it is important that it is accurate.

MAINTENANCE ACTIVITY

The first and most important factor which must be taken into consideration is the level of maintenance activity likely to be taking place in an area. Maintenance trades such as plumbers and electricians are the group who the duty to manage is primarily trying to protect. There are two types of maintenance activity, planned and unplanned. Planned work can be assessed and carried out using procedures and controls to reduce exposure to asbestos. Unplanned work requires the situation to be dealt with as found and the controls that can be applied may be more limited. The frequency of maintenance activities also need to be taken into account in deciding what management action is appropriate.

OCCUPANT ACTIVITY

The activities carried out in an area will have an impact on the risk assessment. When carrying out a risk assessment the main type of use of an area and the activities taking place within it should be taken into account. For example a little used storeroom or an attic will rarely be accessed and so any asbestos is unlikely to be disturbed. At the other end of the scale, in a warehouse lined with asbestos insulating board panels, with frequent vehicular movements, the potential for disturbance of ACMs is reasonably high and this would be a significant factor in the risk assessment. As well as the normal everyday activities taking place in an area, any secondary activities will need to be taken into account.

LIKELIHOOD OF DISTURBANCE

The two factors that will determine the likelihood of disturbance are the extent or amount of the ACM and its accessibility/vulnerability. For example, asbestos soffits outdoors are generally inaccessible without the use of ladders or scaffolding, are unlikely to be disturbed. The asbestos cement roof of a hospital ward is also unlikely to be disturbed, but its extent would need to be taken into account in any risk assessment. However if the same ward had asbestos panels on the walls they would be much more likely to be disturbed by trolley/bed movements.

HUMAN EXPOSURE POTENTIAL

The human exposure potential depends on three factors: the number of occupants of an area, the frequency of use of the area, and the average time each area is in use. For example, a school boiler room is likely to be unoccupied, but may be visited daily for a few minutes. The potential for exposure is much less than say in a classroom lined with asbestos insulating board panelling, which is occupied daily for six hours by 30 pupils and a teacher.

PRIORITY ASSESSMENT ALGORITHMS

Taking all these factors into account in a logical, consistent manner is difficult. Using an algorithm will help you to produce priority assessments that have taken the factors into account in a consistent way. The number of factors relevant at any one site needs to be carefully considered, as the more factors included in an

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms		
		Survey Date:	05 December 2007		
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007		
	Sussex, RH12 4NB	Recommendation:	Page 2 of 3		





Survey Recommendations

algorithm, the lower the influence of the most important risk factors becomes, and this may produce anomalies. For this reason it is recommended that the number of factors that are scored is limited to four, the same as the number of factors in the material assessment. There is no single set of factors that can be recommended that will apply equally to all types of premises. Therefore four general headings have been used and one or more factors can be taken into account and averaged under each heading to suit the circumstances. If you choose to use more than one factor under a general heading, then average the scores under that heading, rounding up where necessary.

The scores from the material assessment (i.e. the condition of the ACM or presumed ACM) are added to the scores of the priority assessment (the likelihood of disturbance), to give the overall risk assessment. Risk assessment scores for different ACMs can then be compared to develop your action plan. In many circumstances the scores will be similar, making decisions more difficult. For example a boiler house with asbestos pipe work insulation in poor condition may get the same or similar risk assessment score to an office with asbestos insulating board in reasonably good condition. This is simply because the ACM in the boiler house received a higher score than the ACM in the office because the ACM in the boiler house was in poor condition. However, the priority assessment for the office will get a higher score than the boiler house since the office is occupied more often. Add the scores together for the material and priority assessments, and you get similar scores. If this is the case then you may decide that the office needs doing first because it is used daily. On the other hand you may decide that the poor condition of the ACM in the boiler house means that it should be done first. If the office was a classroom, the young age of the occupants may be a deciding factor. Algorithms are provided to help you, but they are best guesses and will often require you to make your own additional judgements.

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms		
		Survey Date:	05 December 2007		
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007		
	Sussex, RH12 4NB	Recommendation:	Page 3 of 3		

Printed: 19/12/2007 By: JTEC Environmental Ltd.. Using Multibase software.



SECTION NINE

MATERIAL ASSESSMENT: SUMMARY BY AREA

Material Assessment: Summary by Area

Not Applicable

Area:

Site Name:

Norfolk Arms

Project Number:

AS07220 - Norfolk Arms

Sample Date	Location Ref	Location ID	Drawing Reference	Floor	Room	Asbestos Type	Product Name	Material Risk Score	Material Risk Band	Priority Risk Score	Comments	Action	Survey Type
05/12/07	1	8965	1	Basement	Cellar	Chrysotile	Sink Pad	2	Very Low Risk	3		Apply Warning Labels	T 2
05/12/07	2	8966	2	Ground floor	Bar area	Amosite	Beam cladding	5	Low Risk	5	All structural beams may be clad with ACMs underneath external wood panelling	Apply Warning Labels	T 2
05/12/07	6	8970	6	Ground floor	Bar area	Amosite	Ceiling	5	Low Risk	5		Apply Warning Labels	T 2
05/12/07	7	8971	7	Ground floor	Bar area	Amosite	Beam cladding	5	Low Risk	5	All structural beams may be clad with ACMs underneath external wood panelling	Apply Warning Labels	T 2
05/12/07	8	8972	8	Ground floor	Bar area	Amosite	Beam cladding	5	Low Risk	5	All structural beams may be clad with ACMs underneath external wood panelling	Apply Warning Labels	T 2
05/12/07	9	8973	9	Ground floor	Bar area	Amosite	Ceiling	5	Low Risk	5		Apply Warning Labels	T 2
05/12/07	3	8967	3	Ground floor	Boiler room	Chrysotile	Boiler	3	Very Low Risk	4		Apply Warning Labels	T 2
05/12/07	4	8968	4	Ground floor	Boiler room	Amosite	Ceiling	7	Medium Risk	4		Encapsulate and Apply Warning Labels	T 2
05/12/07	11	8975	11	Ground floor	Boiler room	NADIS	Tiles	0	NADIS	N/A		No Action Required	T 2
05/12/07	12	8976	12	Ground floor	External	Amosite	Soffit	5	Low Risk	2		Apply Warning Labels	T 2
05/12/07	10	8974	10	Ground floor	Kitchen	Amosite	Stair Backing / Cladding	5	Low Risk	5		Apply Warning Labels	T 2
05/12/07	5	8969	5	Ground floor	Lobby	Amosite	Ceiling	7	Medium Risk	5	Material identical to location 4	Re-encapsulate and Apply Warning Labels	T 2
05/12/07	13	8977	13	Ground floor	Porch	Amosite	Ceiling	5	Low Risk	5		Apply Warning Labels	T 2

SECTION TEN

MATERIAL ASSESSMENT (PHOTO)

Material Assessment Record

Action:

	Norfolk Arms, Crawley Road, Roffey, Horsham, We		ient Name:	Hall & Wo	odhouse Ltd
	Sussex, RH12 4NB	Pr	oject Number:	AS07220 -	Norfolk Arms
Location ID:	8965	Survey Type:		T 2	
Location Ref:	1	Product Type:		Resins	
Product:	Sink Pad	Damage:	No visible damage		
Area:	Not Applicable	Treatment:		Resins	
Floor:	Basement	Asbestos Type		Chrysotile	
Room:	Cellar	Identification:		Presumed	
Surveyor Name	e: J D Chilvers	Quantity:			
Drawing Ref:	1	Accessibility:		Medium Accessibi	lity
Asbestos ?	Yes				
Date:	05 December 2007		Materi	al Risk Score	2
Next Inspection	o 04 December 2008		Materi	al Risk Band:	Very Low Risk
TOXE HISPOOLIO			Priority	/ Risk Score:	3



Apply Warning Labels

Material Comments:		
Comments:		

Material Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West

Sussex, RH12 4NB

Client Name: Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID:	8966	Survey Type:	T 2
Location Ref:	2	Product Type:	Asbestos Insulating Board
Product:	Beam cladding	Damage:	No visible damage
Area:	Not Applicable	Treatment:	AIB painted or encapsulated
Floor:	Ground floor	Asbestos Type:	Amosite
Room:	Bar area	Identification:	Presumed
Surveyor Name:	J D Chilvers	Quantity:	5m2
Drawing Ref:	2	Accessibility:	Medium Accessibility
Asbestos ?	Yes		

Next Inspection:

Date:

05 December 2007 05 June 2008

Material Risk Score 5

Material Risk Band: Low Risk Priority Risk Score:

Action: Apply Warning Labels



Material Comments: All structural beams may be clad with ACMs underneath external wood panelling



Material Assessment Record

Action:

Client Name: Hall & Woodhouse Ltd Site Address: Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB Project Number: AS07220 - Norfolk Arms 8967 Survey Type: T 2 Location ID: Location Ref: 3 **Product Type:** Gaskets Product: Boiler Damage: No visible damage Area: Not Applicable Treatment: Composite asbestos materials Ground floor Chrysotile Floor: Asbestos Type: Boiler room Presumed Identification: Room: J D Chilvers Surveyor Name: Quantity: 3 Medium Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 3 05 December 2007 Date: Material Risk Band: Very Low Risk Next Inspection: 04 December 2008 Priority Risk Score:



Apply Warning Labels

Material Comments:		

Material Assessment Record

Date:

Next Inspection:

Client Name: Hall & Woodhouse Ltd Site Address: Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB Project Number: AS07220 - Norfolk Arms 8968 Survey Type: T 2 Location ID: Location Ref: 4 **Product Type:** Asbestos Insulating Board Product: Ceiling Damage: Low damage: Scratches or marks Area: Not Applicable Treatment: Unsealed AIB Ground floor Amosite Floor: Asbestos Type: Boiler room Identified Identification: Room: J D Chilvers 6m2 Surveyor Name: Quantity: Easy Accessibility Drawing Ref: Accessibility: Asbestos? Yes

Action: **Encapsulate and Apply Warning Labels**



Material Comments:	

Material Risk Score

Material Risk Band:

Priority Risk Score:

7

Medium Risk

05 December 2007

04 March 2008

Material Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West

Sussex, RH12 4NB

Client Name: Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID:	8969	Survey Type:	T 2
Location Ref:	5	Product Type:	Asbestos Insulating Board
Product:	Ceiling	Damage:	Low damage: Scratches or marks
Area:	Not Applicable	Treatment:	Unsealed AIB
Floor:	Ground floor	Asbestos Type:	Amosite
Room:	Lobby	Identification:	Identified
Surveyor Name:	J D Chilvers	Quantity:	2m2
Drawing Ref:	5	Accessibility:	Easy Accessibility

Yes

05 December 2007

04 March 2008

Next Inspection:

Asbestos?

Date:

7 Material Risk Score Material Risk Band: Medium Risk Priority Risk Score:

Action: Re-encapsulate and Apply Warning Labels



Material Comments: Material identical to location 4

Material Assessment Record

Next Inspection:

Client Name: Hall & Woodhouse Ltd Site Address: Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB Project Number: AS07220 - Norfolk Arms 8970 Survey Type: T 2 Location ID: Location Ref: 6 **Product Type:** Asbestos Insulating Board Product: Ceiling Damage: No visible damage Area: Not Applicable Treatment: AIB painted or encapsulated Ground floor Amosite Floor: Asbestos Type: Bar area Strongly Presumed Identification: Room: J D Chilvers Surveyor Name: 2m2 Quantity: 6 Easy Accessibility Drawing Ref: Accessibility: Asbestos? Yes Material Risk Score 5 05 December 2007 Date: Material Risk Band: Low Risk



05 June 2008



Material		
Comments:		

Priority Risk Score:

5

Material Assessment Record

Site Address:

Date:

Next Inspection:

Norfolk Arms, Crawley Road, Roffey, Horsham, West

Sussex, RH12 4NB

Client Name: Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID:	8971	Survey Type:	T 2
Location Ref:	7	Product Type:	Asbestos Insulating Board
Product:	Beam cladding	Damage:	No visible damage
Area:	Not Applicable	Treatment:	AIB painted or encapsulated
Floor:	Ground floor	Asbestos Type:	Amosite
Room:	Bar area	Identification:	Presumed
Surveyor Name:	J D Chilvers	Quantity:	5m2
Drawing Ref:	7	Accessibility:	Medium Accessibility
Asbestos ?	Yes		

Material Risk Score 5 Material Risk Band: Low Risk Priority Risk Score:

Action: Apply Warning Labels

05 December 2007

05 June 2008



Material Comments: All structural beams may be clad with ACMs underneath external wood panelling



Material Assessment Record

Site Address:

Date:

Next Inspection:

Norfolk Arms, Crawley Road, Roffey, Horsham, West

Sussex, RH12 4NB

Hall & Woodhouse Ltd Client Name:

Project Number: AS07220 - Norfolk Arms

8972 T 2 Location ID: Survey Type: Location Ref: 8 **Product Type:** Asbestos Insulating Board Product: Beam cladding Damage: No visible damage Not Applicable Treatment: AIB painted or encapsulated Area: Ground floor Amosite Floor: Asbestos Type: Presumed Bar area Identification: Room: J D Chilvers 5m2 Surveyor Name: Quantity: 8 Medium Accessibility Drawing Ref: Accessibility: Asbestos? Yes

Material Risk Score 5 Material Risk Band: Low Risk Priority Risk Score: 5

Action: **Apply Warning Labels**

05 December 2007

05 June 2008



Material Comments: All structural beams may be clad with ACMs underneath external wood panelling

Material Assessment Record

Action:

F			ient Name:	Hall & Woo	dhouse Ltd	
	Norfolk Arms, Crawley Road, Roffey, Horsham, We Sussex, RH12 4NB	est				
		Pi	roject Number:	AS07220 - N	Norfolk Arms	
Location ID:	8973	Survey Type:		T 2		
Location Ref:	9	Product Type:	Asb	estos Insulating Bo	oard	
Product:	Ceiling	Damage:		No visible damage		
Area:	Not Applicable	Treatment:	AIB p	AIB painted or encapsulated		
Floor:	Ground floor	Asbestos Type	:	Amosite		
Room:	Bar area	Identification:		Strongly Presumed		
Surveyor Name	J D Chilvers	Quantity:		15m2		
Drawing Ref:	9	Accessibility:		Easy Accessibility	,	
Asbestos ?	Yes			ſ		
Date:	05 December 2007		Material	Risk Score	5	
Next Inspection	05 June 2008		Material	Risk Band:	Low Risk	
Toxt mopoulor			Priority	Risk Score:	5	



Apply Warning Labels

Material Comments:			

Material Assessment Record

Site Address: Norfolk Arms, Crawley Road, Roffey, Horsham, West

Sussex, RH12 4NB

Asbestos?

Next Inspection:

Date:

Hall & Woodhouse Ltd Client Name:

Project Number: AS07220 - Norfolk Arms

8974 T 2 Location ID: Survey Type: Location Ref: 10 **Product Type:** Asbestos Insulating Board Product: Stair Backing / Cladding Damage: No visible damage Not Applicable Treatment: AIB painted or encapsulated Area: Ground floor Amosite Floor: Asbestos Type: Kitchen Strongly Presumed Identification: Room: J D Chilvers 2m2 Surveyor Name: Quantity: 10 Easy Accessibility Drawing Ref: Accessibility:

> Yes Material Risk Score 5 05 December 2007 Material Risk Band: Low Risk 05 June 2008 Priority Risk Score: 5

Action: **Apply Warning Labels**



Material Comments:

Material Assessment Record

Action:

F		C	ient Name:	Hall & Woo	dhouse Ltd
	Norfolk Arms, Crawley Road, Roffey, Horsham, We Sussex, RH12 4NB	st			
		Pi	roject Number:	AS07220 - N	Norfolk Arms
Location ID:	8975	Survey Type:		T 2	
Location Ref:	11	Product Type:		NADIS	
Product:	Tiles	Damage:		NADIS	
Area:	Not Applicable	Treatment:		NADIS	
Floor:	Ground floor	Asbestos Type	:	NADIS	
Room:	Boiler room	Identification:		Identified	
Surveyor Name	e: J D Chilvers	Quantity:			
Drawing Ref:	11	Accessibility:			
Asbestos ?	No				
Date:	05 December 2007		Material	Risk Score	0
Next Inspection	n: Not Applicable		Material	Risk Band:	NADIS
TTOXE ITISPECTION			Priority	Risk Score:	N/A



No Action Required

Material Assessment Record

Action:

			lient Name:	Hall & Woo	dhouse Ltd	
	Norfolk Arms, Crawley Road, Roffey, Horsham, Wo Sussex, RH12 4NB	est				
		Pr	roject Number:	AS07220 - N	Norfolk Arms	
Location ID:	8976	Survey Type:		T 2		
Location Ref:	12	Product Type:	Asb	estos Insulating Bo	oard	
Product:	Soffit	Damage:		No visible damage		
Area:	Not Applicable	Treatment:	AIB p	AIB painted or encapsulated		
Floor:	Ground floor	Asbestos Type	:	Amosite		
Room:	External	Identification:		Presumed		
Surveyor Name	J D Chilvers	Quantity:		2m2		
Drawing Ref:	12	Accessibility:	M	ledium Accessibili	ty	
Asbestos ?	Yes			Г		
Date:	05 December 2007		Material	Risk Score	5	
Next Inspection	• 05 June 2008	I	Material	Risk Band:	Low Risk	
Tront mopoduon			Priority	Risk Score:	2	



Apply Warning Labels

Material			
Material Comments:			

Material Assessment Record

Date:

Next Inspection:

Site Address: Norfolk Arms, Crawley Road, Roffey, Horsham, West

Sussex, RH12 4NB

Hall & Woodhouse Ltd Client Name:

Project Number: AS07220 - Norfolk Arms

8977 T 2 Location ID: Survey Type: Location Ref: 13 **Product Type:** Asbestos Insulating Board Product: Ceiling Damage: No visible damage Not Applicable Treatment: AIB painted or encapsulated Area: Ground floor Amosite Floor: Asbestos Type: Porch Identification: Strongly Presumed as previous sample Room: J D Chilvers Surveyor Name: 2m2 Quantity: 13 Easy Accessibility Drawing Ref: Accessibility: Asbestos? Yes

Material Risk Score 5 Material Risk Band: Low Risk Priority Risk Score: 5

Action: **Apply Warning Labels**

05 December 2007

05 June 2008



Material Comments:

SECTION ELEVEN

BULK IDENTIFICATION REPORT

BULK IDENTIFICATION REPORT

Client:	Hall & Woodhouse Ltd	Date Samples	05/12/2007
		Received:	
Client	The Brewery, Blandford St Mary, Dorset, DT11 9LS	Date Samples	10/12/2007
Address:		Analysed:	
Site	Norfolk Arms, Crawley Road, Roffey, Horsham, West Susse	x, RH12 4NB	
Address:			
F.A.O:			Page 1 of 1

METHOD USED:

Samples of material referenced below, have been examined to determine the presence of asbestos fibres, using a method of polarising light microscopy and centre stop dispersion staining, based on H.S.E,s MDHS 77. NOTE: We cannot be held responsib for the accuracy and competence of samples taken by third parties. Under these circumstances we cannot be held responsible for the interpretation of the results shown.

	Location ID	Sample Location	Fibre Type
4	8968	Ground floor, Boiler room, Ceiling	Amosite
5	8969	Ground floor, Lobby, Ceiling	Amosite
11	8975	Ground floor, Boiler room, Tiles	NADIS

REPORT RAISED BY:	
Signed:	Print:



SECTION TWELVE

PRIORITY ASSESSMENT: SUMMARY BY AREA

Priority Assessment: Summary by Area

Site Name:

Norfolk Arms

Project Number:

AS07220 - Norfolk Arms

Area: No	t Ap	oplic	able
----------	------	-------	------

Sample Date	Location Ref	Location ID	Drawing Reference	Floor	Room	Comments	Normal Occupant Activity	Likelihood Of Disturbance	Human Exposure Potential	Maintenance Activity	Risk Score
05/12/07	1	8965	1	Basement	Cellar		0	1	1	1	3
05/12/07	2	8966	2	Ground floor	Bar area		1	1	2	1	5
05/12/07	6	8970	6	Ground floor	Bar area		1	1	2	1	5
05/12/07	7	8971	7	Ground floor	Bar area		1	1	2	1	5
05/12/07	8	8972	8	Ground floor	Bar area		1	1	2	1	5
05/12/07	9	8973	9	Ground floor	Bar area		1	1	2	1	5
05/12/07	3	8967	3	Ground floor	Boiler room		1	1	1	1	4
05/12/07	4	8968	4	Ground floor	Boiler room		1	1	1	1	4
05/12/07	12	8976	12	Ground floor	External		0	1	0	1	2
05/12/07	10	8974	10	Ground floor	Kitchen		1	1	2	1	5
05/12/07	5	8969	5	Ground floor	Lobby		1	1	2	1	5
05/12/07	13	8977	13	Ground floor	Porch		1	1	2	1	5

SECTION THIRTEEN

PRIORITY ASSESSMENT RECORD

Priority Assessment Record

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Site Address:

Project Number:

AS07220 - Norfolk Arms

Location ID: 8965 Location Ref: Sink Pad Product: Not Applicable Area: **Basement** Floor: Cellar Room: J D Chilvers Surveyor Name: 1 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		3
Material Assessment Score (supplied by surveyor):	Very Low Risk	2
Total of Material and Priority Assessment Scores:		5

Priority Assessment: Page 1 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8966 2 Location Ref: Beam cladding Product: Not Applicable Area: Ground floor Floor: Bar area Room: J D Chilvers Surveyor Name: 2 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Large rooms or well-ventilated areas	1	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	>10	3	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>1 to <3 hours	1	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 2 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8967 3 Location Ref: Boiler Product: Not Applicable Area: Ground floor Floor: Boiler room Room: J D Chilvers Surveyor Name: 3 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	Small items strings gaskets	0	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Weekly	2	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:	4
Material Assessment Score (supplied by surveyor):	3
Total of Material and Priority Assessment Scores:	7

Priority Assessment: Page 3 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8968 4 Location Ref: Ceiling Product: Not Applicable Area: Ground floor Floor: Boiler room Room: J D Chilvers Surveyor Name: 4 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Weekly	2	average
Average time area is in use:	<1 hour	0	1
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		4
Material Assessment Score (supplied by surveyor):	Medium Risk	7
Total of Material and Priority Assessment Scores:		11

Priority Assessment: Page 4 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8969 5 Location Ref: Ceiling Product: Not Applicable Area: Ground floor Floor: Room: Lobby J D Chilvers Surveyor Name: 5 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Opti a region

Priority Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Outdoors	0	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	4 to 10	2	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Medium Risk	7
Total of Material and Priority Assessment Scores:		12

Priority Assessment: Page 5 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8970 6 Location Ref: Ceiling Product: Not Applicable Area: Ground floor Floor: Bar area Room: J D Chilvers Surveyor Name: 6 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Large rooms or well-ventilated areas	1	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	4 to 10	2	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>1 to <3 hours	1	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 6 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8971 7 Location Ref: Beam cladding Product: Not Applicable Area: Ground floor Floor: Bar area Room: J D Chilvers Surveyor Name: 7 Drawing Ref: Asbestos? Yes Date: 05 December 2007 CONTRACTOR OF TAXABLE PARTY.

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Large rooms or well-ventilated areas	1	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	>10	3	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>1 to <3 hours	1	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 7 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8972 8 Location Ref: Beam cladding Product: Not Applicable Area: Ground floor Floor: Bar area Room: J D Chilvers Surveyor Name: 8 Drawing Ref: Asbestos? Yes Date: 05 December 2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Low disturbance	1	1
Likelihood Of Disturbance:			
Location:	Large rooms or well-ventilated areas	1	
Accessibility:	Usually inaccessible or unlikely to be disturbed	0	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	>10	3	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>1 to <3 hours	1	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 8 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

8973 Location ID: 9 Location Ref: Ceiling Product: Not Applicable Area: Ground floor Floor: Room: Bar area J D Chilvers Surveyor Name: 9 Drawing Ref: Asbestos? Yes Date: 05 December 2007 06/12/2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Large rooms or well-ventilated areas	1	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	4 to 10	2	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>1 to <3 hours	1	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 9 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8974 10 Location Ref: Stair Backing / Cladding Product: Not Applicable Area: Ground floor Floor: Room: Kitchen J D Chilvers Surveyor Name: 10 Drawing Ref: Asbestos? Yes Date: 05 December 2007

CENT 2: 2007

Priority Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Rooms up to 100 m2	2	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Daily	3	average
Average time area is in use:	>1 to <3 hours	1	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 10 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8976 12 Location Ref: Soffit Product: Not Applicable Area: Ground floor Floor: External Room: J D Chilvers Surveyor Name: 12 Drawing Ref: Asbestos? Yes Date: 05 December 2007

2011 212022

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Rare disturbance	0	average
Secondary activities for area:	Rare disturbance	0	0
Likelihood Of Disturbance:			
Location:	Outdoors	0	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	1 to 3	1	
Frequency of use of area:	Infrequent	0	average
Average time area is in use:	<1 hour	0	0
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		2
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		7

Priority Assessment: Page 11 of 1.



Priority Assessment Record

Site Address:

Norfolk Arms, Crawley Road, Roffey, Horsham, West Sussex, RH12 4NB

Client Name:

Hall & Woodhouse Ltd

Project Number:

AS07220 - Norfolk Arms

Location ID: 8977 13 Location Ref: Ceiling Product: Not Applicable Area: Ground floor Floor: Room: Porch J D Chilvers Surveyor Name: 13 Drawing Ref: Asbestos? Yes Date: 05 December 2007

66/12/2007

Priority
Comments:

Priority Assessment Algorithm			
Assessment factor	Variable(s) selected	Score for each	Overall score
Normal Occupant Activity:			
Main type of activity in area:	Low disturbance	1	average
Secondary activities for area:	Rare disturbance	0	1
Likelihood Of Disturbance:			
Location:	Outdoors	0	
Accessibility:	Occasionally likely to be disturbed	1	average
Extent/Amount:	<=10 m2 or <=10 m pipe run	1	1
Human Exposure Potential:			
Number of occupants:	4 to 10	2	
Frequency of use of area:	Daily	3	average
Average time area is in use:	<1 hour	0	2
Maintenance Activity:			
Type of maintenance activity:	Minor disturbance	0	average
Frequency of maintenance activity	<=1 per year	1	1

Total Priority Assessment Score:		5
Material Assessment Score (supplied by surveyor):	Low Risk	5
Total of Material and Priority Assessment Scores:		10

Priority Assessment: Page 12 of 1.



SECTION FOURTEEN

EXCLUDED AREAS

Excluded Areas

1 Managers / Tenants accommodation

Client Name:	Hall & Woodhouse Ltd	Project Number:	AS07220 - Norfolk Arms
		Survey Date:	05 December 2007
Site Address:	Norfolk Arms, Crawley Road, Roffey, Horsham, West	Printed On:	19 December 2007
	Sussex, RH12 4NB	Excluded Areas:	Page 1 of 1



